



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@gmail.com

Re-Inspection Certificate Fire Extinguishers

Cert.No : 022/MJAP/PMK/V/26

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 21 Mei 2026
- Name Of Ship : CB. PAN MARINE 9

No.	Type	Volume	Quantity	Working Code
1.	DRY POWDER	6,0 Kg	3 Cyls	1, 2, 3
2.	CO2 PORTABLE	5,0 Kg	2 Cyls	1, 2, 3
3.	CO2 PORTABLE	6,8 Kg	2 Cyls	1, 2, 3
4.	FOAM AFFF	9,0 Ltr	8 Cyls	1, 2, 3

THIS IS TO CERTIFY that

1. The above mentioned fire extinguisher has been inspected, repaired, and retested in compliance with following scope of work :

- | | |
|---------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Weight / Content | 5) Condemned |
| 3) Recharged | 6) New Supply |

2. On completion, the fire extinguishers is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels).

3. The condition of the above fire extinguishers has been found to satisfaction and in good condition

- Date Of next inspection : 20 Mei 2027



For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate CO2 SYSTEM

Cert.No : 006/MJAP/CO2/VI/26

• Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 21 Mei 2026
• Name Of Ship : CB. PAN MARINE 9

Cylinder No.	Cylinder Serial No.	Last Hydro Test Date	Tare Weight (Kg)	Gross Weight (Kg)	Volume (Kg)	Type Of Cylinder	Working Code
1.	HK 056070	-	74.1	119.1	45	CO2	1.2
2.	HK 056087	-	74.9	119.9	45	CO2	1.2
3.	HK 056133	-	74,8	119.8	45	CO2	1.2

THIS IS TO CERTIFY that

1. The above mentioned CO2 System has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|---------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Weight / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the CO2 System is are Re-assemble back to Operation Condition and satisfaction in good condition.

• Date Of next inspection : 20 Mei 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara

Telp. (021) 440 8538 Fax. (021) 440 8538

E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate Breathing Apparatus

Cert.No : 006/MJAP/BA/V/26

• Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 21 Mei 2026
• Name Of Ship : CB. PAN MARINE 9

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	167792	250 Bar	200 Bar	6,0 Ltr	AIR	1, 2, 3
2.	001152	250 Bar	200 Bar	6,0 Ltr	AIR	1, 2, 3
3.	154082	250 Bar	200 Bar	6,0 Ltr	AIR	1, 2, 3
4.	001684	250 Bar	200 Bar	6,0 Ltr	AIR	1, 2, 3

THIS IS TO CERTIFY that


1. The above mentioned Breathing Apparatus has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Breathing Apparatus is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

• Date Of next inspection : 20 Mei 2027

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate Emergency Escape Breathing Device

Cert.No : 005/MJAP/EEBD/V/26

• Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 21 Mei 2026
• Name Of Ship : CB. PAN MARINE 9

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	000240	250 Bar	200 Bar	3,0 Ltr	AIR	1, 2, 3
2.	001195	250 Bar	200 Bar	3,0 Ltr	AIR	1, 2, 3
3.	054344	250 Bar	120 Bar	3,0 Ltr	AIR	1, 2, 3

THIS IS TO CERTIFY that

1. The above mentioned Emergency Escape Breathing Device (EEBD) has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Emergency Escape Breathing Device (EEBD) is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

• Date Of next inspection : 20 Mei 2027

ORIGINAL

For and on behalf of

FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA



PT. MEGAJAYA ABADI PERKASA

GENERAL SUPPLIER & MARINE SAFETY, SERVICE LIFERAFT,
RUBBER BOAT, LIFE JACKET & FIRE EXTINGUISHER

Jl. Kebantenan III No.11 Semper Timur - Jakarta Utara
Telp. (021) 440 8538 Fax. (021) 440 8538
E-mail : megajayaabadi@ymail.com

Re-Inspection Certificate Medical Oxygen Device

Cert.No : 003/MJAP/MO/V/26

- Customer : PT. PAN MARITIME WIRA PAWITRA • Date : 21 Mei 2026
• Name Of Ship : CB. PAN MARINE 9

No.	Cylinder Serial No.	Test Pressure	Working Pressure	Cylinder Capacity	Type Of Cylinder	Working Code
1.	060	250 Bar	200 Bar	2,0 Ltr	AIR	1, 2, 3
2.	352415	250 Bar	200 Bar	2,0 Ltr	AIR	1, 2, 3
3.	352614	250 Bar	200 Bar	2,0 Ltr	AIR	1, 2, 3

THIS IS TO CERTIFY that

1. The above mentioned Medical Oxygen Device (MO) has been inspected, refilled, and retested in compliance with following scope of work :

- | | |
|-----------------------------|-----------------------|
| 1) Service / Inspected | 4) Hidrostatic Tested |
| 2) Check Pressure / Content | 5) Condemned |
| 3) Refilling | 6) New Supply |

2. On completion, the Medical Oxygen Device (MO) is are Re-assemble back to Operation Condition (Sealed with Pins and Control Labels) and satisfaction in good condition.

- Date Of next inspection : 20 Mei 2027

ORIGINAL

For and on behalf of



FERIYANSYAH

Approved Signatory for chief Inspector
At PT. MEGAJAYA ABADI PERKASA